

Inspection Photos

API: 071-06190

Operator: OGRIS OPERATING LLC

Inspection Date: 9/8/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06190 | Date: 9/8/2022

Inspection Photos



Photo 1. There is vehicle rutting and an area where is pooling at the location. This area needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06190 | Date: 9/8/2022

Inspection Photos



Photo 2. There is a water leak coming from the wellhead that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06190 | Date: 9/8/2022