

Inspection Photos

Location Name: Baldy Creek Federal #2-20 Pad & Spill/Release

Location ID: #322436 & Spill/Release ID: #482408

Inspection Date: August 30, 2022



COGCC Field Inspection
39.43522, -107.46228, 8176.5ft, 347°
08/30/2022 9:51:15 AM

Photo #1 – Wellhead with sign, note horizontal separator in background.



COGCC Field Inspection
39.43522, -107.46227, 8232.5ft, 246°
08/30/2022 9:51:18 AM

Photo #2 – Unused tank on pad has been subject to unused equipment removal corrective actions since at least 2013 (per FIR doc #670200599).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Baldy Creek Federal #2-20 Pad & Spill/Release

Location ID: #322436 & Spill/Release ID: #482408

Inspection Date: August 30, 2022



Photo #3 – Additional unused production equipment on location.



Photo #4 – Unused horizontal separator on location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Baldy Creek Federal #2-20 Pad & Spill/Release

Location ID: #322436 & Spill/Release ID: #482408

Inspection Date: August 30, 2022



**Photo #5 – View of wellhead and tank battery from east.
This area was impacted by produced water reported under
COGCC Spill/Release ID #482408.**



**Photo #6 – Areas downhill from Spill/Release ID #482408
require additional Site Investigation to assess for potential
impacts.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources