


Inspection Photos  
Location Name: Simon Land and Cattle 21U-1R 2  
Location ID: 334326



IMG 01  
Well sign




IMG 02  
Location overview





**IMG 03**  
Location overview



**IMG 04**  
2" pipe





**IMG 05**  
**0.5" tubing**



**IMG 06**  
**Erosion channel**





IMG 07

Tank sign



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources