

Inspection Photos

September 9, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313281

Location Name: Kaline Unit-612N94W /23NESW

Inspection Document #: 702800685

Moffat County, CO

NESW Section 23 T12N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Kaline Unit-612N94W /23NESW

Location ID: 313281



Photo 1. Photo taken to the east, on the access road shows debris from a locator wire is present. All debris and equipment must be removed per Rule 1004.a.



Photo 2. Photo taken at the south of the Location shows debris from a locator wire is present. All debris and equipment must be removed per Rule 1004.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800685

Inspection Photos

Location Name: Kaline Unit-612N94W /23NESW

Location ID: 313281



Photo 3. Photo taken to the east of the Location shows the access road has been reclaimed.



Photo 4. Photo taken to the south shows an overview of the reclaimed Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800685

Inspection Photos

Location Name: Kaline Unit-612N94W /23NESW

Location ID: 313281



9/9/22
+40.983550,-107.918605
5° N

Photo 5. Photo taken from the south of the Location shows the vegetation community of the reclaimed Location is dominated by native perennial grasses and occasional native shrubs.



9/9/22
+40.983550,-107.918605
332° NW

Photo 6. Refer to Photo 5 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800685

Inspection Photos

Location Name: Kaline Unit-612N94W /23NESW

Location ID: 313281



Photo 7. Photo taken from the north of the Location shows the vegetation community on the reclaimed Location (right) and off Location in the reference area (left).



Photo 8. Photo taken from the north of the Location shows the vegetation community of the reclaimed Location is dominated by native perennial grasses and occasional native shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800685

Inspection Photos
Location Name: Kaline Unit-612N94W /23NESW
Location ID: 313281



Photo 9. Photo shows reference area vegetation to the south of the Location.

