

Final Reclamation and Stormwater Inspection

Date: 09/08/2022

Operator: KIMBARK OIL & GAS COMPANY - 47700

Location ID: 394559

Inspection Document #: 696105417

Morgan County, CO

NWSE Section 23 T5N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 1. Access road photo taken south of location, facing north. Photo illustrates access road has not been reclaimed and presence of weedy annual vegetation (e.g. russian thistle, kochia).

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 2. Location photo taken from western portion, facing east. Photo illustrates non-uniform vegetation cover resulting in bare soil, outlined in red.

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 3. Facing west from eastern portion of location, see comments in photo 2.

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 4. Taken from northeast portion of location, facing north. Photo illustrates a pit remains on location and has not been reclaimed.

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 5. Close up photo of pit, see comments in photo 4.

Inspection Photos
Location Name: MCCLARNAN #2
Location ID: 394559



Photo 6. Reference area photo taken west of access road, facing west.