

**Inspection Photos**  
**Location Name: Mustang 12-26 Pad**  
**Location ID: 452874**



**Photo #1 Location**



**Photo #2 Bird protector appears to be missing**