

Inspection Photos

September 9, 2022

Operator: Crowheart Energy LLC - #10776

Location ID: 313162

Location Name: Kaline SWD-612N94W /23NENW

Inspection Document #: 702800692

Moffat County, CO

NENW Section 23 T12N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Kaline SWD-612N94W /23NENW
Location ID: 313162



Photo 1. Photo taken from the south, at the Location entrance shows an overview of the Location.



Photo 2. Photo taken from the north shows an overview of the Location including interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800692

Inspection Photos
Location Name: Kaline SWD-612N94W /23NENW
Location ID: 313162



Photo 3. Photo shows the tank battery sign. Operator name has been updated. Emergency number on sign has been updated and is in service. Sign does not comply with Rule 605; Telephone number for local emergency services (911 where available) and the public road used to access the tank battery site are not posted.



Photo 4. Photo shows the well sign. Operator name has been updated. Emergency number on sign has been updated and is in service.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800692

Inspection Photos

Location Name: Kaline SWD-612N94W /23NENW

Location ID: 313162



Photo 5. Photo taken from the center of the Location shows an overview of the interim area. Bare ground dominates. The shorter plants which dominate the photo are kochia (annual undesirable plant species). The taller green and yellow plants are rabbitbrush (native shrubs) which are scattered.



Photo 6. Photo taken from the west of the Location shows an overview of the interim area. The red polygon indicates a patch of western wheatgrass (native, perennial grass) which appears to have been seeded but is rarely present. The plant throughout the photo is kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800692

Inspection Photos

Location Name: Kaline SWD-612N94W /23NENW

Location ID: 313162



Photo 7. Photo taken from the west of the Location shows interim area vegetation. Photo also shows trash/debris.



Photo 8. Refer to Photo 7 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800692