

Inspection Photos and Issue Report

9/12/2022

Operator: PLUG NICKEL OIL COMPANY INC -
10556

Location #315713
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: PLUG NICKEL OIL COMPANY INC - 10556

Location #315713



September 12, 2022



September 12, 2022

Photo 1: Photos taken from the west end of the Location, facing northeast and east. Photos provide an overview of the Location; final reclamation of the Location has not been conducted in accordance with 1004 standards

Inspection Photos
Operator Name: PLUG NICKEL OIL COMPANY INC - 10556
Location #315713



Photo 2: Photo shows remaining secondary containment berm; location has not been reclaimed.

Inspection Photos
Operator Name: PLUG NICKEL OIL COMPANY INC - 10556
Location #315713



September 12, 2022



September 12, 2022

Photo 3: Photos taken from the east end of the Location facing west. Photos show Location has not been reclaimed in accordance with 1004 standards.

Inspection Photos

Operator Name: PLUG NICKEL OIL COMPANY INC - 10556

Location #315713



Photo 4: Noxious weeds observed on Location and access road.



Inspection Photos

Operator Name: PLUG NICKEL OIL COMPANY INC - 10556

Location #315713



Photo 5: Access road has not been reclaimed in accordance with 1004 standards



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources