

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 1 WH sign.

Photo 2 WH



Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 3 Pump Jack



Photo 4 Trash in pump house



Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 5 Trash in pump house

Photo 6 TB sign

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 7 Crude tank

Photo 8 PW tank

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 9 HHs and ECD.

Photo 10 Gas Meter Run.