

Inspection Photos  
Location Name: McElvain-Harmon 1A  
Location ID: 311923



IMG 01  
Well sign



IMG 02  
Location overview





**IMG 03**

**Erosion near wellhead**



**IMG 04**

**Erosion near produced water**





**IMG 05**

**Erosion near gas meter run**



**IMG 06**

**Erosion near gas meter run**