

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

Location sign.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
Location Name: River Ranch A Pad
Location ID: 336014
Spill/Release ID: 480927
Remediation Project #21574
Inspection Date: August 11, 2022

Dripping bull plug on the northwest steel AST.

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



Aug 11, 2022 1:03:27
+39.5387N -107.698



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



Aug 11, 2022 1:04:04
+39.5386N -107.698



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: River Ranch A Pad
Location ID: 336014
Spill/Release ID: 480927
Remediation Project #21574
Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species and
absence of vegetation.**



Aug 11, 2022 1:04:50
+39.5385N -107.697



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

Oil absorbent boom located in the marshy area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

Oil absorbent boom located in the marshy area (red area).



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Remediation Project #21574

Inspection Date: August 11, 2022

**Spill/release area, note the
undesirable plant species.**



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources