

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /42-11 Frac Pad

Location ID: 334956



Photo #7637 From entrance to location.



Photo #7638 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /42-11 Frac Pad

Location ID: 334956



Photo #7634 Multiple loadlines open ended.



Photo #7635 Multiple loadlines open ended.