

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 1 – Sign at Entrance



Photo 2 – Wellheads

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Colorado Oil and Gas Conservation Commission
40.63834, -104.02204, 4879.8ft, 167°
09/15/2022 13:14:25

Photo 3 – Trash Dumpsters NOT Covered



Colorado Oil and Gas Conservation Commission
40.63826, -104.02217, 4872.9ft, 180°
09/15/2022 13:14:34

Photo 4 – Unused Equipment

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 5 – Unused Parts and Equipment



Photo 6 – Unused Parts and Equipment

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 7 – Unused Propane Bottles



Photo 8 – Unused Structure

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 9 – Stained Soil at 31-2




Photo 10 – Stained Soil at 31-3

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 11 – Unused Parts



Photo 12 – Stained Soil at 31-6

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 13 – Stained Soil at 31-7



Photo 14 – Tank Battery

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 15 – Separators



Photo 16 – Compressors

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 17 – Wildlife Netting missing on Day Tank



Photo 18 – Wildlife Netting missing on Day Tank

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 19 – Electrical Equipment



Photo 20 – VRUs

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 21 – ECDs



Photo 22 – LACT

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 23 – VRT and Tanks – Labels Missing



Photo 24 – Labels missing on ALL Tanks

Inspection Photos
Location Name: Allred Federal 8-59-30 PAD
Location ID: 476815



Photo 25 – Labels Missing on ALL Tanks



Photo 26 – Gas Lift Injection Meter House