

# Final Reclamation Inspection

July 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 333322

Inspection Document #: 701900458

SESE Section 29 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McLeod 2  
Location ID: 333322



**Photo 1.** 2021 aerial imagery of the well pad and access road. Note: tank battery highlighted in blue is associated with the McCleod 2-29B well API #123-24146.

Inspection Photos  
Location Name: McLeod 2  
Location ID: 333322



**Photo 2.** Overview photo of the well pad taken at ground level from the eastern edge facing west.

Inspection Photos  
Location Name: McLeod 2  
Location ID: 333322



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: McLeod 2  
Location ID: 333322



**Photo 4.** Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad shows stunted crop growth and does not appear consistent with adjacent reference area (see photo 5).

Inspection Photos  
Location Name: McLeod 2  
Location ID: 333322



Photo 5. well pad reference area.