

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 1 – Wellheads



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 3 – Unused Parts On North side of Location




Photo 4 – Unused Chemical Tank – Trash

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 5 – Trash/Debris



Photo 6 – Unused Hose

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Colorado Oil and Gas Conservation Commission
40.64232, -104.18158, 4922.1ft, 154°
09/15/2022 13:38:33

Photo 7 – Gas Lift Injection Meter Houses



Colorado Oil and Gas Conservation Commission
40.64169, -104.18214, 4914.2ft, 135°
09/15/2022 13:39:24

Photo 8 – Compressor

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 9 – Production Equipment



Photo 10 – Production Equipment

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 11 – VRT, Air Unit, Tanks



Photo 12 – Labels Missing

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 13 – Tank Battery



Photo 14 – Tank Battery Sign

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 15 – Tank Battery



Photo 16 – Maintenance Tank

Inspection Photos
Location Name: Kummer PC LE23-62HN PAD
Location ID: 432075



Photo 17 – Compressor



Photo 18 – Unused Methonal Maintenance Tank