

Inspection Photos

API: 071-07766

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 2. This area of the road needs additional work due to signs of stormwater flowing past the diversion ditch on the right which is beginning to create erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing back to the south west. There is erosion beginning to occur along the roadsides and additional BMP's are needed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing northwest toward road turns down the hill side into the canyon. There is some initial signs of erosion down the road which may require additional BMP's such as a water bar.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 5. The road was graded down to the canyon bottom and erosion was repaired. This area has a long stretch without culverts and may require additional stabilization or vegetation establishment. This area was previously observed to be eroded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 6. Facing east along the access road. This area may need some hand work to get stormwater better directed toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 7. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 8. Facing southwest toward the location. The location is recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022