

Inspection Photos

API: 071-09178

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 1. Drone aerial photo facing west toward the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 2. Drone aerial photo facing northwest toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing west down at the location. A large berm was installed at the bottom of the location. There appears to be deep erosion into the berm where rock was not installed. BMP's such as rock check dams may be need to prevent accelerated erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing east down at the location. A large berm was installed at the bottom of the location. The area to the right of the berm does not appear to have vegetation establish and may need to be hand seeded this fall.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 5. Facing toward the upper portion of the location. There is vegetation beginning to establish however additional BMP's may need to be installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022

Inspection Photos



Photo 6. Facing northwest toward the recontoured location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 9/16/2022