

Inspection Photos

API: 071-07508

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing southwest along the access road. Stormwater is bypassing the culvert causing erosion down the road. Lat/Long:37.28091,-104.90745



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 9/16/2022

Inspection Photos



Photo 2. Further down the road. There is erosion along the road side that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 9/16/2022