

Inspection Photos

API: 071-07791

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing northwest toward the beginning portion of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 2. The culvert along the road have been cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing northeast along the access road. The road is not recontoured. Fallen rocks have been moved off the roadway since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing east along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 5. Facing east toward the location. The location has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022

Inspection Photos



Photo 6. A portion of the location was regraded and dozer track. Additional BMP's (e.g. wattles) may be needed as there are some signs of erosion beginning to occur.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 9/16/2022