

Inspection Photos
Location Name: Magdalene Clare 33-7-2 2
Location ID: 325477



IMG 01
Well sign



IMG 02
Weeds at wellhead



IMG 03
Weeds at separator



IMG 04
Tank capacity is not labeled



IMG 05
Weeds at produced water tank.