

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 303303

Inspection Document #: 696105437

Yuma County, CO

SESW Section 24 T4S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: LANGENDOERFER #14-24

Location ID: 303303



Photo 1. Taken from county road, facing north. Photo illustrates old access road entrance into field; it appears access road has been reclaimed with disturbance area reflective of reference area crop. Red outline is approximate location of entrance.

Inspection Photos

Location Name: LANGENDOERFER #14-24

Location ID: 303303



Photo 2. Taken from center portion of location, facing southeast; close up. Photo illustrates an area approximately 10' x 10' in size that is subsided, void of uniform vegetation cover, and not reflective of reference area crop.



Inspection Photos

Location Name: LANGENDOERFER #14-24

Location ID: 303303



Photo 3. Facing west, see comments in photo 2.

Inspection Photos

Location Name: LANGENDOERFER #14-24

Location ID: 303303



Photo 4. Reference area photo taken east of location, facing east.