

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 303231

Inspection Document #: 696105438

Yuma County, CO

SWSE Section 24 T4S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 1. Taken from southern portion of location, facing north. Photo illustrates that disturbance area is not reflective of reference area with lack of uniform vegetation cover and patches of bare soil and annual weedy vegetation observed.

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 2. Taken east of location, facing west. See comments in photo 1.

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 3. Taken from northern portion of location, facing south. Photo illustrates well location and access road in background. See comments in photo 1.

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 4. Taken west of location, facing east. See comments in photo 1.



Photo 5. Close up photo of location vegetation.

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 6. Close up photo of bare soil observed on location.

Inspection Photos
Location Name: OSMUS #C4-24
Location ID: 303231



Photo 7. Reference area photo taken east of location, facing east.