

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 303494

Inspection Document #: 696105439

Yuma County, CO

NESE Section 24 T4S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 1. Taken off of adjacent access road, facing southeast. Photo illustrates tank battery location has not been reclaimed with presence of weedy annual vegetation, road base/gravel, and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 2. Facing south from access road, see comments in photo 1.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 3. Taken west of tank battery location, facing east. See comments in photo 1.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 4. Reference area east of battery location, facing southeast.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 5. Taken from well location, facing west. Photo illustrates disturbance area has failed to revegetate and is not reflective of reference area crop (sugar beets). Location is predominantly russian thistle with some desirable growth observed.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 6. Taken south of location, facing north. See comments in photo 5.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 7. Taken west of location, facing east. See comments in photo 5.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 8. Facing north. Red outline illustrates bare soil.



Photo 9. Close up photo of bare soil.

Inspection Photos
Location Name: OSMUS #9-24
Location ID: 303494



Photo 10. Reference area north of well location, facing north.