

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 303393

Inspection Document #: 696105440

Yuma County, CO

SENE Section 12 T4S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 1. Taken from county road, facing west. Photo illustrates access road (outlined in red) appears to have been reclaimed with perennial crop reflective of reference areas.



Photo 2. Taken from location, facing northwest. Photo illustrates that the disturbance area has failed to revegetate and is not reflective of reference area levels. Annual weedy vegetation (e.g. russian thistle) observed and outlined in red.

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 3. Close up photo, see comments in photo 2.

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 4. Facing northwest, see comments in photo 2.

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 5. Facing south, see comments in photo 2.

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 6. Facing south, see comments in photo 2.

Inspection Photos
Location Name: COOK #8-12
Location ID: 303393



Photo 7. Reference area photo taken east of location , facing northeast. Photo illustrates uniform vegetation cover.