

Inspection Photos

September 15, 2022

Operator: KP Kauffman Company Inc - #46290

Location ID: 324771

Location Name: McCallum Unit-69N79W /3SENE

Inspection Document #: 702800701

Jackson County, CO

SENE Section 3 T9N R79W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCallum Unit-69N79W /3SENE
Location ID: 324771



Photo 1. Photo taken from the north shows an overview of the Location. Plant species in the photo are annual undesirable plant species/weeds. Seeded plant species were not observed.



Photo 2. Photo taken from the north shows an overview of the Location. Plant species in the photo are annual undesirable plant species/weeds.

Inspection Photos
Location Name: McCallum Unit-69N79W /3SENE
Location ID: 324771



Photo 3. Photo taken from the south of the Location show the access road has not been reclaimed.

Inspection Photos

Location Name: McCallum Unit-69N79W /3SENE

Location ID: 324771



Photo 4. Photo taken from the north of the Location shows the soil surface. Plant species in the photo include Kochia, Russian thistle and tumbling saltweed (annual, undesirable plant species/weeds).



Photo 5. Photo taken from the west of the Location shows the soil surface. Plant species in the photo include Kochia, Russian thistle and tumbling saltweed (annual, undesirable plant species/weeds). Soils appear compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800701

Inspection Photos

Location Name: McCallum Unit-69N79W /3SENE

Location ID: 324771



Photo 6. Photo taken from the south of the Location shows flowline equipment remains.



Photo 7. Photo taken from the west of the Location shows pipe equipment remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800701