

Inspection Photos and Issue Report

9/20/2022

Operator: LARAMIE ENERGY LLC #10433

Location #312417

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



September 20, 2022



September 20, 2022

Photo 1: Photos provide overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



September 20, 2022

Photo 2: Photo taken from the Location, and shows areas within the site where uniform desirable vegetative establishment/germination is not progressing towards 1004 uniform standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



September 20, 2022



September 20, 2022

Photo 3: Photo shows a patch of Undesirable Plant Species (Halogeton) established on the Location. Noxious plant Species not observed within the immediate, adjacent reference areas.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



Photo 4: Photos examples showing areas along the access road where uniform desirable vegetative establishment/germination is not progressing towards 1004 uniform standards. Additional reclamation efforts required within these areas of the road.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



September 20, 2022

Photo 5: Photo example of areas along the access road that are progressing towards 1004 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #312417



Photo 6: Photo example of the adjacent reference areas.