

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: ENERGY QUEST II LLC - 10490

Location ID: 337058

Inspection Document #: 696105433

Yuma County, CO

NWNW Section 10 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRENNER #10-4
Location ID: 337058



Photo 1. Taken from location, facing south. Photo illustrates location has not been reclaimed with presence of bare soil resulting from non-uniform vegetation cover and annual weedy vegetation (e.g. kochia) outlined in red..

Inspection Photos
Location Name: BRENNER #10-4
Location ID: 337058



Photo 2. Facing northeast, see comments in photo 1.

Inspection Photos
Location Name: BRENNER #10-4
Location ID: 337058



Photo 3. Facing northwest, see comments in photo 1.

Inspection Photos
Location Name: BRENNER #10-4
Location ID: 337058



Photo 4. Taken from eastern portion of location, facing east. Photo illustrates soil erosion exiting off location; no visible stormwater or erosion control BMPs observed during inspection.

Inspection Photos
Location Name: BRENNER #10-4
Location ID: 337058



Photo 5. Reference area photo taken west of location, facing southwest. Predominantly buffalo grass.