

Final Reclamation Inspection

August 1st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 331583

Inspection Document #: 701900504

NWNE Section 21 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fickel 31-21
Location ID: 331583



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Fickel 31-21
Location ID: 331583




Photo 2. Overview photo of the well pad, access road, and reference area taken from the southern edge, facing north, using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.




Photo 3. Overview photo of the tank battery taken from the southern edge facing north using a drone. Note: tank battery shows stunted crop growth and does not appear consistent with adjacent reference crop area indicated by blue arrow. Culvert location also displayed and indicated by black arrow (see photo 5).

Inspection Photos
Location Name: Fickel 31-21
Location ID: 331583



Photo 4. Overview ground photo of the tank battery taken from the western edge facing east. Photo shows stunted crop growth at the tank battery disturbance area.

Inspection Photos
Location Name: Fickel 31-21
Location ID: 331583



Photo 5. Removed culvert left on site located at the northern edge of the tank battery.