

# Final Reclamation Inspection

August 2nd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306229

Inspection Document #: 701900508

NWNE Section 15 T6N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 1.** 2021 aerial imagery of the well pad and access road. Note: the tank battery highlighted in blue is associated with the Harvester 42-15 well API #123-24268.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad shows stunted crop growth and significant bare ground compared to adjacent reference area (see photo 5).

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 5.** Well pad reference area.