

Final Reclamation Inspection

August 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 305383

Inspection Document #: 701900528

NESW Section 28 T7N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383




Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383




Photo 2. Overview photo of the well pad, access road, tank battery and reference area taken from the southern edge facing north using a drone. Note: well pad, access road and tank battery do not appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383



Photo 3. Overview photo of the tank battery taken at ground level from the western edge facing east.