

Inspection Photos
Location Name: Josey 12-8
Location ID: 318902



Photo 1 – Heater Treater and ECD



Photo 2 – Tank Battery

Inspection Photos
Location Name: Josey 12-8
Location ID: 318902



Photo 3 – Tank Battery Sign



Photo 4 – Missing Capacity Label

Inspection Photos
Location Name: Josey 12-8
Location ID: 318902



Photo 5 – Berm has been compromised by Livestock



Photo 6 – Pumping Unit

Inspection Photos
Location Name: Josey 12-8
Location ID: 318902



Photo 7 – Wellhead Sign




Photo 8 – Wellhead

Inspection Photos
Location Name: Josey 12-8
Location ID: 318902



Photo 9 – Fence in disrepair in NW corner