

# Final Reclamation Inspection

August 5th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323074

Inspection Document #: 701900553

SWSE Section 20 T4N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 1.** 2021 aerial imagery of the well pad, access road and tank battery.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north. Note: well pad falls within a harvested alfalfa field.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 3.** Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 4.** Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 5.** Stalk taken from the middle of the well pad disturbance.  
Appears consistent with stalk taken from reference area (see photo 6).



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 6.** Well pad reference area and stalk.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 7.** Overview photo of the tank battery taken at ground level from the eastern edge facing west.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 8.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, left photo facing east.



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 9.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south and right photo facing west. Note: tank battery does not appear consistent with adjacent reference area (see photo 10).



Inspection Photos  
Location Name: Peschel 34-20  
Location ID: 323074



**Photo 10.** Tank battery reference area.