

Final Reclamation Inspection

August 17, 2022

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 482899

Inspection Document #: 697504186

Weld County, CO

NENE Section 33 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



Photo 1. Photo taken from an unused tank battery, facing West. Photo illustrates equipment has not been removed.



Photo 2. Photo taken from an unused tank battery, facing East. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504186

Inspection Photos
Location Name: 33-2N-68W NENE Tank Battery Loc
Location ID: 482899



Photo 3. Close up photo taken illustrating the Operator ownership.

Inspection Photos

Location Name: 33-2N-68W NENE Tank Battery Loc

Location ID: 482899



Photo 4. Photo taken from an unused tank battery, facing South. See comments under Photo 1.



Photo 5. Photo taken from an unused tank battery, facing North. See comments under Photo 1.