

Inspection Photos

September 16, 2022

Operator: Bonanza Creek Energy Operating Company
LLC - #8960

Location ID: 324667

Location Name: North Park Coal-69N78W /18NWSW

Inspection Document #: 702800720

Jackson County, CO

NWSW Section 18 T9N R78W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 1. Photo shows one of two spur roads which converge into the Location access road. Photo shows the eastern portion of unreclaimed road which is approximately 40 yards long.



Photo 2. Photo shows one of two spur roads which converge into the Location access road. Photo shows the western portion of unreclaimed road which is approximately 30 yards long.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 3. Photo taken to the north shows the majority of the Location access road (~0.26 miles) has been reclaimed and is vegetated with perennial grasses.



Photo 4. Photo taken to the northwest shows an overview of the reclaimed Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 5. Photo taken to the east shows an overview of the reclaimed Location. Portions of the Location are dominated by perennial grasses. Areas at the west of the Location have poor perennial establishment and high cover of annual undesirable plant species/weeds (red polygon).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 6. Photo taken from the northwest of the Location shows an area with poor perennial establishment and high cover of annual undesirable plant species/weeds (tumbling saltweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 7. Photo taken from the west of the Location shows an area with poor perennial establishment and high cover of annual undesirable plant species/weeds (tumbling saltweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 8. Photo shows an area at the east of the Location which is dominated by desirable perennial grasses.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 9. Photo shows a variety of trash/debris from the Location.



Photo 10. Photo shows a metal rod sticking out of the ground at the northwest of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 11. Photo taken to the north, on the Location access road shows an abandoned utility pole which must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720

Inspection Photos

Location Name: North Park Coal-69N78W /18NWSW

Location ID: 324667



Photo 12. Photo taken to the north of the Location shows reference area vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800720