



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #1 Produced water discharge from production pits to Seeping Spring Tributary. Note the presence of hydrocarbon sheen and hydrocarbon on; booms, rocks and vegetation.



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #2 Produced water discharge from production pits to Seeping Spring Tributary. Note the presence of hydrocarbon sheen and hydrocarbon on rocks and vegetation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #3 Produced water discharge from production pits to Seeping Spring Tributary. Note the presence of hydrocarbon sheen and hydrocarbon on soil and vegetation.



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #4 Weir at discharge. Note Hydrocarbon staining in Weir and Hydrocarbon sheen on water.





Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #5 Effluent discharge. Note: hydrocarbon sheen on water and hydrocarbon in vegetation.





Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #6 Effluent discharge. Note: hydrocarbon sheen on water and hydrocarbon in vegetation.





Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #7 Algal mat in discharge creek, hydrocarbon sheen on water.





Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Facility 312756
Inspection Date: 9/20/2022
All Photos taken by COGCC Staff

Photo #



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources