

Inspection Photos and Issue Report

9/22/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #335455

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335455



Photo 1: Photos taken from the sediment trap on the west end of the Location. Photos show stormwater runoff has resulting in gully degradation at the inlet. Hard hat in left photo used for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335455



September 22, 2022



September 22, 2022

Photo 2: Continued from photo 1. Photo shows erosion degradation at the sediment trap.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335455



Photo 3: Photo taken from the former UIC facility site on the Location. Photo shows erosion degradation occurring along areas of the road leading to the former facility.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335455



Photo 4: Photos examples showing Undesirable and Noxious Plant species observed on the location. Photos show Common Mullein plants, including rosettes (photo right).