

Inspection Photos

API: 071-07384

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07384 | Date: 9/23/2022

Inspection Photos



Photo 1. There are still noxious weeds along the access road that need to be controlled. The red arrow points to Houndstongue which is a biennial.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07384 | Date: 9/23/2022

Inspection Photos



Photo 2. Facing south toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07384 | Date: 9/23/2022

Inspection Photos



Photo 3. Facing toward the cut slope. It appears some of the noxious weeds have wilted from weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07384 | Date: 9/23/2022

Inspection Photos



Photo 4. View of noxious weeds Houndstong which is a biennial. Many of the plants have produced seed. Ongoing weed control will be required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07384 | Date: 9/23/2022