

# Inspection Photos

API: 071-07696

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07696 | Date: 10/4/2022

## Inspection Photos



**Photo 1.** Facing south along the access road. There is significant erosion occurring across the road in this area. This area has no culvert and stormwater from the drainage washes across the road. Lat/Long:37.10005,-104.76045



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07696 | Date: 10/4/2022

## Inspection Photos



**Photo 2.** Facing toward the eroded area along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07696 | Date: 10/4/2022

## Inspection Photos



**Photo 3.** Facing southeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07696 | Date: 10/4/2022