


# Inspection Photos

Location Name: Pine River 2-29 #2

Location ID:



IMG 01  
Well sign



IMG 02  
Location overview





**IMG 03**

**Erosion channel on access road**



**IMG 04**

**Erosion channel on access road**





**IMG 05**

**Erosion channel on access road**



**IMG 06**

**Erosion channel on access road**





**IMG 07**

**Erosion channel on access road**



**IMG 08**

**Weeds on berms**





**IMG 09**  
**Weeds at separator**



**IMG 10**  
**Weeds at wellhead**