

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 1 – Wellhead



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 3 – Chemical Tank missing Labels



Photo 4 – ECD and Separators

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 5 – Separators



Photo 6 – Compressor

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 7 – Day Tank Wildlife Netting in disrepair



Photo 8 – Compressor and Gas Meters

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 9 – Separators and VRU



Photo 10 – Tank Battery

Inspection Photos
Location Name: Kaufman PC GL 20-68HN
Location ID: 429749



Photo 11 – Tank Battery Sign at Entrance