

Final Reclamation Inspection

September 28, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306513

Inspection Document #: 697504257

Weld County, CO

NESW Section 24 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DALTON-67N66W 24NESW
Location ID: 306513



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location, flowline and associated offsite tank battery. Flowlines removed per Form 44.

Inspection Photos
Location Name: DALTON-67N66W 24NESW
Location ID: 306513



Photo 2. COGCC drone orthomosaic imagery illustrating the well location, flowline and associated offsite tank battery. There appears to be a vegetative issue along a portion of the flowline (red arrows).

Inspection Photos

Location Name: DALTON-67N66W 24NESW

Location ID: 306513



Photo 3. COGCC drone orthomosaic imagery illustrates an ~200' flowline length where crop growth is not reflective of reference areas.



Inspection Photos

Location Name: DALTON-67N66W 24NESW

Location ID: 306513



Photo 4. Google Earth aerial imagery from 9/7/2016 illustrates there may have been previous vegetative issues associated with the flowline area.



Inspection Photos
Location Name: DALTON-67N66W 24NESW
Location ID: 306513



Photo 5. Photo taken from the associated offsite tank battery, facing South. Photo illustrates all equipment has been removed and the tank battery is not within crop production.



Photo 6. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 5.