

Final Reclamation Inspection

September 28, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306513

Inspection Document #: 697504257

Weld County, CO

NESW Section 24 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DALTON-67N66W 24NESW
Location ID: 306513



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location, flowline and associated offsite tank battery. Flowlines removed per Form 44.



Photo 2. COGCC drone aerial imagery illustrating the well location, flowline and associated offsite tank battery. Crop growth appears reflective along the flowline and well location but there are vegetative issue observed at the tank battery.

Inspection Photos
Location Name: DALTON-67N66W 24NESW
Location ID: 306513



Photo 3. Photo taken from the associated offsite tank battery, facing West. Photo illustrates an approximate 30' x 50' area of stunted corn growth.