

Inspection Photos and Issue Report

10/06/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #323839

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #323839



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the reclamation areas from west, northwest, northeast, to east. Revegetation of the Location is predominantly desirable species, and establishment is uniform per 1004 standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #323839



October 6, 2022



October 6, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #323839



October 6, 2022



October 6, 2022

Photo 3: Photos show areas along the access road/location entrance that remains predominantly bare; vegetation within these areas is not progressing towards 1004 uniform standards.