

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #1 Inadequate Berms



Photo #2 Inadequate Berms



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #3 Inadequate Berms



Photo #4 Inadequate Berms



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #5 Inadequate Berms/ Unused chemical totes



Photo #6 Unused Equipment/ Trash

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121




Photo #7 Unused Equipment



Photo #8 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #9 Trash



Photo #10 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #11 Unused Equipment



Photo #12 Unused Equipment/ Trash



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #13 Trash



Photo #14 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #15 Unused Equipment



Photo #16 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #17 Unused Equipment



Photo #18 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #19 Unused Equipment



Photo #20 Unused Equipment



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #21 Unused Equipment



Photo #22 Trash

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #23 Unused Equipment/ Trash



Photo #24 Unused Equipment



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #25 Unused Equipment



Photo #26 Trash



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #27 Unused Equipment



Photo #28 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #29 Unused Equipment



Photo #30 Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #31 Trash



Photo #32 Oily Waste