

**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery Sign**

**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 3 – ECD**



**Photo 4 – Label has faded no longer visible**

**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 5 – Tank Battery**



**Photo 6 – Heater Treater**



**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 7 – Flare – Disconnected**



**Photo 8 – Pumping Unit**

**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 9 – Wellhead**



**Photo 10 – Gas Engine**



**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 11 – Wellhead Sign**



**Photo 12 – Inside Heater Building**

**Inspection Photos**  
**Location Name: Varra 12-9-66-1H**  
**Location ID: 423403**



**Photo 13 – Inside Heater Building**