

Inspection Photos

API: 055-06068

Operator: OXY USA INC

Inspection Date: 10/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing southeast along the road near the location. Red arrow points to Diffuse knapweed which was recently spray. The knapweed has already produced seed. Weed control should be performed sooner before seed dispersal.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos




Photo 2. Facing southeast at the location. There is blue dye on plants from weed spraying. The plants shown however are not weeds but native Rubber rabbitbrush. Operator should consult with contractor as to what is being sprayed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos



Photo 3. Facing south at the location. There is blue dye on plants from weed spraying. The plants shown however are not weeds but Basin wildrye grass. Operator should consult with contractor as to what is being sprayed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos



Photo 4. Blue dye observed on native grass.



Photo 5. Blue dye observed on Rubber rabbit brush.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos



Photo 7. Facing east toward the fill slope of the location. There are noxious weeds in this area that need to be controlled. There was no blue dye observed indicating no weed control was performed. Red arrow → Canada thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022

Inspection Photos



Photo 8. Canada thistle observed in previous photos has already dispersed seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 10/6/2022