

# Inspection Photos and Issue Report

10/11/2022

Operator: LARAMIE ENERGY LLC - 10433

Location #312741

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



**Photo 1:** Photos taken from the southwest end of the Location. Photos provide an overview of the Location from northwest, north, northeast to southeast. Photos show Location has not been reclaimed per 1004 Rules including, but not limited to, removal of gravel, compaction alleviation (cross ripping to a minimum depth of 18 inches), contouring/regrading, replacement of soils and revegetation activities. Brown vegetation observed in photo is predominantly Undesirable Weedy Plant Species such as Russian Thistle.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



October 11, 2022



October 11, 2022

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



**Photo 3:** Gravel/road base remaining on Location.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



**Photo 4:** Photos taken from the southeast end of the Location, facing northwest and north. Photo shows Undesirable Plant Species established throughout the Location. Weed management efforts inadequate on the Location. Vegetation mostly dead, is considered debris and requires removal.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



**Photo 5:** Photo shows a pit remaining on the southeast end of the Location.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #312741



October 11, 2022

**Photo 6:** Photo taken from the north end of the Location, facing east. Photo shows fill slopes; location has not been recontoured/regraded and reclaimed.