

# Final Reclamation and Stormwater Inspection

Date: 10/07/2022

Operator: PINTAIL PETROLEUM LTD - 70430

Location ID: 411327

Inspection Document #: 696105485

Yuma County, CO

NENE Section 13 T2S R48W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327



**Photo 1.** Taken from location, facing east. It appears final reclamation activities have occurred with no visual evidence of oil and gas equipment. Annual weedy vegetation (e.g. kochia) was observed throughout the location, outlined in red.

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327



**Photo 2.** Facing north, see comments in Photo 1.

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327



**Photo 3.** Facing west, see comments in Photo 1.

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327




**Photo 4.** Facing south, see comments in Photo 1.

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327



**Photo 5.** Aerial imagery taken from Google Earth illustrating pre-disturbance image of location, circa 1998. This is the most current imagery prior to any oil and gas development.

Inspection Photos  
Location Name: III L FARMS #1  
Location ID: 411327



**Photo 6.** Aerial imagery taken from Google Earth illustrating post oil and gas development image of location, circa 2004. This image shows a disturbance in the immediate vicinity of the well location.