

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 1 – Stained Soil at Wellheads

Photo 2 – North Heater Treaters

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 3 – Tank Battery



Photo 4 – Labels has faded no longer visible

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 5 – Tank Battery Sign



Photo 6 – South Water Tank - Label Fading and peeling away

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 7 – Tank Battery



Photo 8 – South Heater Treater

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 9 – ECD



Photo 10 – Flare

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 11 – Weeds in Interim Reclamation Area

Photo 12 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 13 – Weeds in Interim Reclamation Area

Photo 14 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 15 – Weeds in Interim Reclamation Area

Photo 16 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: State 2-36-9-61 PAD
Location ID: 433993



Photo 17 – Weeds in Interim Reclamation Area