

Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 414794

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Inspection Document #: 702800805

Garfield County, CO

NWNW Section 33 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Location ID: 414794



Photo 1. Photo taken from the northeast shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800805

Inspection Photos

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Location ID: 414794



Photo 2. Photo taken from the interim area shows bull thistle (List B Noxious).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800805

Inspection Photos

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Location ID: 414794



Photo 3. Photo taken from the southeast shows the eastern interim area colonized by perennial grasses. Photo also shows the original cut slopes on the east end of the Location remain evident.



Photo 4. Photo taken from east shows the original cut slope remains, with a stormwater ditch at its base. Contouring will be necessary to address cut slopes/stormwater BMPs during final reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800805

Inspection Photos

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Location ID: 414794



10/10/22
+39.490876, -107.567877
69° E

Photo 5. Photo taken from the west shows a slope drain which has been lined with angular riprap and geotextile fabric.



10/10/22
+39.489803, -107.567594
356° N

Photo 6. Photo taken from the south shows access road stormwater controls measures.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800805

Inspection Photos

Location Name: GGU FED (MDP PAD #2)/11A-33-691

Location ID: 414794



Photo 7. Photo taken from the south shows a tank battery which is separate from the northern portion of the Location. Slopes are colonized by perennial grasses.



Photo 8. Refer to Photo 7 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800805